


# **Storm Survey for Tornadoes over Lincoln County on 8/17/2015**

**Two Brief EF1 Tornadoes touched down late Monday afternoon near Genoa. Maximum Wind Speeds with both the Tornadoes were estimated in the 90 to 95 mph range. Both Tornadoes traveled under one tenth of a mile and were less than 50 yards wide.**

## 0.5 Miles south of Genoa

Outbuilding  
before  
Tornado



Outbuilding destroyed after Tornado





An aerial photograph showing a rural landscape. In the lower-left, there is a large, dark-roofed shed. To its right is a smaller, white-roofed house. The surrounding area is a mix of green grass and bare, brownish ground. A dirt road runs along the bottom of the frame. A highway with yellow lane markings is visible at the top.

**Vacant House  
next door.**

**Vacant House with Minor Damage**



# 1 Mile southeast of Genoa



Grain Silo's before Tornado




Grain Silo's after Tornado



# Radar Picture at 455 pm on August 17, 2015 from KFTG

## Base Reflectivity at 0.5 Degrees



## Storm Relative Velocity at 0.5 Degrees

